











A		M6*90	10
B			10
C		Φ6*70	12
D		M6*120	1
E		M6	2
F		Φ8*30	10
G		Φ6*90	4
H		Φ7*50	6
I		4*30	52
J			1
K			1





STEP:1




F		Φ8*30	10
---	---	-------	----




STEP:2




A		M6*90	4
B			4



STEP:3




A		M6*90	6
B			6
D		M6*120	1
E		M6	2
K			1

STEP:4



C		Φ6*70	12
G		Φ6*90	4
H		Φ7*50	6

STEP:5



I	 4*30	52
---	--	----