

Ø 5,0 mm

D1 = 5,0 + 0,08 / - 0,15 mm

D2 = 9,5 + 0 / - 1,0 mm

k = 1,1 + / - 0,3 mm

d = 2,9 mm

P = ≥ 27,0 mm

L = + 1,0 / - 0,2 mm

 5,1 mm

	F-Max				
5,0 x 6,0 mm	11,4 mm	1,0 - 2,5 mm	70801 50600	2575 N	3255 N
5,0 x 8,0 mm	13,4 mm	2,5 - 4,0 mm	70801 50800		
5,0 x 10,0 mm	15,4 mm	4,0 - 6,0 mm	70801 50100		
5,0 x 12,0 mm	17,4 mm	6,0 - 8,0 mm	70801 50120		
5,0 x 14,0 mm	19,4 mm	8,0 - 10,0 mm	70801 50140		
5,0 x 16,0 mm	21,4 mm	10,0 - 11,5 mm	70801 50160		
5,0 x 18,0 mm	23,4 mm	11,5 - 13,5 mm	70801 50180		
5,0 x 20,0 mm	25,4 mm	13,5 - 15,0 mm	70801 50200		
5,0 x 22,0 mm	27,4 mm	15,0 - 17,0 mm	70801 50220		
5,0 x 25,0 mm	30,4 mm	17,0 - 20,0 mm	70801 50250		
5,0 x 30,0 mm	35,4 mm	20,0 - 25,0 mm	70801 50300		
5,0 x 35,0 mm	40,4 mm	25,0 - 30,0 mm	70801 50350		
5,0 x 40,0 mm	45,4 mm	30,0 - 35,0 mm	70801 50400		